

General Information

Total Number of Active UST Facilities: 5,567

Total Number of Active UST compartments: 16,978

Summary Information For On-Site Inspections

Number of UST Facilities Inspected: 2,634

Inspection Period: 10/1/2007 to 9/30/2008

Percent Compliance

Release Prevention: 84.63%

Release Detection: 85.71%

Combined Compliance: 76.67%

Note: Tanks, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs and those deferred in 40 CFR 280.10(c). On-site inspections measure compliance with release detection and release prevention (significant operational compliance, state regulations, Subtitle I, etc.).

Summary Information For Releases:

Number of Confirmed UST Releases: 120

Release Reporting Period: 10/1/2007 to 9/30/2008

Summary Information For Release Sources and Causes

Source/Location			Cause															
			Not Listed		Spill		Overfill		Human Error		Pipe Failure		Mechanical Failure		Unknown		Other	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Not Listed	75	62.50%	42	56%	3	4%	1	1%	2	3%	2	3%	2	3%	22	29%	1	1%
Dispenser	9	7.50%	0	0%	1	11%	0	0%	0	0%	3	33%	2	22%	3	33%	0	0%
Other	3	2.50%	0	0%	1	33%	1	33%	0	0%	0	0%	1	33%	0	0%	0	0%
Piping	9	7.50%	0	0%	0	0%	0	0%	1	11%	5	56%	2	22%	1	11%	0	0%
STR	1	0.83%	0	0%	0	0%	0	0%	0	0%	1	100%	0	0%	0	0%	0	0%
Tank	9	7.50%	1	11%	0	0%	2	22%	0	0%	0	0%	0	0%	6	67%	0	0%
Unknown	14	11.67%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	14	100%	0	0%
Total	120		43	36%	5	4%	4	3%	3	3%	11	9%	7	6%	46	38%	1	1%

Note: **Release, source and cause** information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12. This report reflects data from releases reported to the Department during the time period of the report. Source and cause data were collected using on-site inspections and reports from facilities.